

YAAK SCHOOL DISTRICT #24

30117 Yaak River Road
Troy, Montana 59935

SDMS Document ID



2009517

Telephone
406-295-4805

June 25, 2002

**EPA Information Center
Office Copy**

Paul Peronard
U.S. Environmental Protection Agency
Region 8
999 18th St., Suite 300
Denver, Colorado 80202-2466

Dear Mr. Peronard,

The EPA gathered samples for asbestos testing at the Yaak School, in Lincoln County, Montana, on April 10, 2001 and again in July of 2001. You met with Sue Janssen, a member of the board of trustees at that time, to go over the results of the tests. Sue requested that you make a written report on the results of testing at the school and any recommendations for the trustees. The trustees are awaiting this documentation to include in the public records of the school.

Please review the testing done at the Yaak school and send a written report to the trustees, at the above address, explaining the results of the testing and any response recommended by your office.

Thank you very much for your attention in this matter.

Sincerely,

Shirley Karuzas, clerk



295-5269

At/Dust/Water

Sample ID	Remarks	Type	Location	Material	Date	Status	AIBDA										ISO Construction (As-Built/Dust - Buried)												Other As-Built									
							Access					Opening					Structure Insulated					Structure Insulated					Structure Insulated					Structure Insulated						
							Admission	Admission	Admission	Admission	Admission	Opening	Opening	Opening	Opening	Opening	Length	Length	Length	Length	Length	Length	Length	Length	Length	Length	Length	Length	Length	Length	Length	Length	Length	Length	Length	Length	Length	
							Admission	Admission	Admission	Admission	Admission	Opening	Opening	Opening	Opening	Opening	Length	Length	Length	Length	Length	Length	Length	Length	Length	Length	Length	Length	Length	Length	Length	Length	Length	Length	Length	Length	Length	
1-02237	Libby Public School	Yes	Yes	Yes	10-Apr-01	10-Apr-01						50	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0			
1-02238	Libby Public School	Yes	Yes	Yes	10-Apr-01	10-Apr-01						10	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0			
1-02239	Libby Public School	Yes	Yes	Yes	10-Apr-01	10-Apr-01						10	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0			
1-02240	Libby Public School	Yes	Yes	Yes	10-Apr-01	10-Apr-01						10	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0			
1-02241	Libby Public School	Yes	Yes	Yes	10-Apr-01	10-Apr-01						10	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0			
1-02243	Libby Public School	Yes	Yes	Yes	10-Apr-01	10-Apr-01						10	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0			
1-02244	Libby Public School	Yes	Yes	Yes	10-Apr-01	10-Apr-01						50	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0			

Soil Bulk

Sample ID	Scenario/Field ID	Task	Yaak School Location	At attic access Sub Location	Media Type	Matrix	Category	Date	PLM Tremolite-Actinolite (%)	Q Ch
1-02242	1-02242		Yaak School	At attic access	Bulk Insulation		IFS - Field	10-Apr-01	0	

**LIBBY MONTANA SITE INVESTIGATION
FIELD SAMPLE DATA SHEET FOR
DUST**

Sheet No: D- 000151

Address or Location ID: Yaak School

Scenario No.: _____

GPS (if no address available): Northing _____ Easting _____

B 4001

Owner: Yaak School District # 24

Land Use Category: Residential (School) Commercial Mining Other (_____)

Date: 4-10-01

Sampling Team: PES (Bria Stewart)

Data Item	Cassette 1	Cassette 2	Cassette 3
Field ID Number			
Index ID	1-02238	1-02239	1-02240
Category (circle)	<u>(FS)</u> Blank	<u>(FS)</u> Blank	FS <u>(Blank)</u>
Location Description	<u>Entry way Carpet</u>	<u>3 Windows Sills</u>	<u>Blank</u>
Sample area (cm ²)	<u>300</u>	<u>300</u>	
Flow Meter Type	<u>Rotometer</u>	<u>Rotometer</u>	
Flow Meter ID Number	<u>003359</u>	<u>003359</u>	
Pump ID Number	<u>508643</u>	<u>508643</u>	
Start-Time	<u>0910</u>	<u>0918</u>	
Start-Flow (L/min)	<u>2.0</u>	<u>2.0</u>	
Stop-Time	<u>0916</u>	<u>0924</u>	
Stop-Flow (L/min)	<u>2.0</u>	<u>2.0</u>	
Pump fault?	<u>(No)</u> Yes	<u>(No)</u> Yes	No Yes
Field Comments			

File

Sheet No: 1 - 0136

LIBBY MONTANA SITE INVESTIGATION
FIELD SAMPLE DATA SHEET FOR
BULK INSULATION

Address or Location ID: Park School

GPS (if no address available): Northing _____ Easting _____

Owner: Park School District # 24

Land Use Category: Residential School Commercial Mining Other (_____)

Date: 4-10-01

Sampling Team: PES (Bria Stewart)

Data Item	Sample 1	Sample 2	Sample 3
Field ID Number			
Index ID	1-02242		
Matrix Type	Insulation	Insulation	Insulation
Category (circle)	FS FD	FS FD	FS FD
Description of Sampling Location	At attic access		
Field Comments	Insulation is throughout attic.		

LIBBY MONTANA SITE INVESTIGATION FIELD SAMPLE DATA SHEET FOR STATIONARY AIR

Address or Location ID: Yaak School

GPS (if no address available): Northing _____ Easting _____

Owner: Yaak School District #24Land Use Category: Residential School Commercial Mining Other (_____)Site Visit Date: 4-10-01Sampling Team: PES (Brian Stewart)

Data Item	Cassette 1	Cassette 2	Cassette 3
Field ID Number			
Index ID	1-02243	1-02244	1-02237
Category (circle)	<u>FS</u> Rep _____ Blank _____	FS Rep _____ <u>Blank</u>	FS Rep _____ <u>Blank</u>
Matrix Type (circle)	<u>Indoor</u> Outdoor _____	<u>Indoor</u> Outdoor _____	<u>Indoor</u> Outdoor _____
Location Description	<u>Center of Main Classroom</u>	<u>Blank</u>	<u>Blank</u>
Flow Meter Type	<u>Rotameter</u>		
Flow Meter ID No.	<u>003359</u>		
Pump ID Number	<u>1341</u>		
Start-Date	<u>4-10-01</u>		
Start-Time	<u>0905</u>		
Start-Counter	<u>NA</u>		
Start-Flow (L/min)	<u>9.0</u>		
Stop-Date	<u>4-10-01</u>		
Stop-Time	<u>0912</u> <u>1610</u>		
Stop-Counter	<u>NA</u>		
Stop-Flow (L/min)	<u>9.0</u>		
Pump fault?	<u>(No)</u> Yes	No Yes	No Yes
MET Station onsite?	<u>(No)</u> Yes	No Yes	No Yes
Field Comments			

* Sample Index ID's changed

1-02235 to 1-02243

1-02236 to 1-02244

due to accidental repeat in ID #'s

df 4/12/01